

Nº 5182

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14
37
✓

DATE INSPECTED 7-16-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 235' — 12' deep

HOUSE NO. 1836

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

12th St. S.E.

← N.



SIGNED

John Chover
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8-27-48 D.C.

REMARKS: _____

Nº 5182

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/19 1948

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED A. R. Russell

TO TAP San

SEWER, ON THE E.

SIDE

OF 12th SE

AVE., TYPE OF STREET Dist

THE PREMISES BEING LOT NO. 50 (Outside City Limits)

HOUSE NO. 1836

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.