

14
37
✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 5183

DATE INSPECTED 7-17-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 144'

HOUSE NO. 1817

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 150'
CURB LINE AND DEPTH 7' deep

SIZE OF PIPE USED _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

12TH ST. S.E.



SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 8-37-48 Dec

REMARKS: _____

Nº 5183

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/19 1948

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED L. E. (Cass)

TO TAP San

SEWER, ON THE W

SIDE

OF 12th S.E.

AVE.,
ST.,

TYPE OF STREET dirt

THE PREMISES BEING LOT NO. 7169

HOUSE NO. 1817

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.