

Nº 5194

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-25-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1125

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

79' 3' deep

WAS LATERAL AT CURB? Yes



WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

11TH ST. N.E.



SIGNED

John E. Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-4-48

REMARKS: _____

Nº 5194

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/24 1948

RECEIVED OF A. J. Deana

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Robert Walters

TO TAP San

SEWER, ON THE W

SIDE

OF 117th E

AVE.,
ST.,

TYPE OF STREET Paved

THE PREMISES BEING LOT No. 7430

HOUSE No. 1125

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.