FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

0 -1-10		
DATE INSPECTED 8-24-48	IF SO HOW AND LOCATION FROM	
DATE INSPECTED	FIRST MANHOLE DOWN STREAM	
HOUSE NO. 226	THO I MARITOLL DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7 Deep.
WAS LATERAL AT CURB? Yes	1.	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR ASTON	
		N
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	/,7
		^
	72 /2 7' Deep	
	7'Deep 1/2' 60	utside edge of Walk
	1	Main Sewer in
SIGNED R. J. Juny	I from 1/# > C FILED AT ENGINEER'S OFFICE	Hawthorne Oct 6-1942
INSPECTOR FOR CIT	'Y 	TOTAL STATE OF THE
REMARKS:		
REMARKS.		Strain of the st

Nº 5195

PERMIT TO TAP SEWER

0 0 6	MASSILLON, OHIO,	5 1948
RECEIVED OF I all and	leman	FEE OF S
FOR WHICH PERMISSION IS GRANTED Charles) nemeth	
TO TAP LAN SEWER	, on the	SIDE
Hautharne Make. TYP	E OF STREET QUE	<i>D</i>
THE PREMISES BEING LOT NO. 7779	, House No. 22	6
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E No. 2323. DULY PASSED BY	THE CITY COUNCIL, AND

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.