

Nº 5197

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

7-3
7
3
✓

DATE INSPECTED 8-30-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 724

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 3' 4' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

TAYLOR AVE. S.W.

← N →



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-4-48

REMARKS: _____

Nº 5197

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

her
1-
MASSILLON, OHIO, 8/30 1928
RECEIVED OF Howard Harlocker FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED same
TO TAP San SEWER, ON THE E. SIDE
OF Taylor St. AVE., TYPE OF STREET Alley
THE PREMISES BEING LOT NO. ~~4682~~ 4618, HOUSE NO. 724

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.