

Deep line laid for cellar drainage.
Existing Lateral not changed.

Nº 5206

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

8
52

DATE INSPECTED 10-8-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

See Sketch 8' Deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. E. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-11-48

REMARKS:

Nº 5206

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/5 1948

RECEIVED OF A. J. Mann

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED A J Mann

TO TAP sanitary

SEWER, ON THE north

SIDE

OF State Ave

AVE.,
ST.,

TYPE OF STREET oil

THE PREMISES BEING LOT NO. 7823

HOUSE NO. 2

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymona Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.