


8-37

Nº 5212

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-21-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1531SIZE OF PIPE USED 8"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 9' 11'6" deepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN YesNAME OF CONTRACTOR Astom

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

121 ST N.E.

SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-30-48

REMARKS: _____

Nº 5212

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

H. Aston MASSILLON, OHIO, 10/19 1948
RECEIVED OF Robert Deenbar FEE OF 2.00
FOR WHICH PERMISSION IS GRANTED Robert Deenbar
TO TAP San SEWER, ON THE W. SIDE
OF 1st N.E. AVE., TYPE OF STREET Paved.
THE PREMISES BEING LOT NO. 10155, HOUSE NO. 1531

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.