

N^o 5214

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

10
36
✓

DATE INSPECTED 11-6-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE ~~BY~~ ^{UP} STREAM

16'

5 deep

HOUSE NO. 316

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Smart,

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

2ND ST S.W.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11-13-48

REMARKS:

Sewer in alley in rear of house.

Nº 5214

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/27 1918

RECEIVED OF Ben Harper

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Amos W. Schoenfeld

TO TAP San

SEWER, ON THE E

SIDE

OF 2nd SW

AVE.,
ST.,

TYPE OF STREET Alley

THE PREMISES BEING LOT NO. 1088

HOUSE NO. 316

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Smart

Sewer on alley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.