Nº 5218

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-24-45	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		•
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8'deef
WAS LATERAL AT CURB?		•
WAS ATTACHED TO MAIN 45	NAME OF CONTRACTOR ASTON	P-
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	Transport
Janice A	ve. N.E.	16
		1 9 de of
<u> </u>	<u>/</u> .	3
	A 116	2 Sde of
SIGNED John Thu	FILED AT ENGINEER'S OF	FICE 10-30-48
INSPECTOR FOR CITY		
11-111111111111111111111111111111111111		and the state of t

Nº 5218

PERMIT TO TAP SEWER

	10/27	C.
RECEIVED OF	MASSILLON, OHIO, FEE OF \$	1946
OR WHICH PERMISSION IS GRANTED	me	
	R, ON THE	SIDE
4 1	PE OF STREET	
VORK TO BE DONE IN ACCORDANCE WITH ORDINANC		COUNCIL AND

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.