


Nº 5241

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-22-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 323SIZE OF PIPE USED 4" up DISTANCE FROM FIRST MANHOLE
~~DOWN~~ STREAM TO DITCH AT CURB LINE AND DEPTH 150' 7' deepWAS LATERAL AT CURB? yesWAS ATTACHED TO MAIN yesNAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Cherry ST. N.E.

SIGNED

John Chinner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

Feb. 1, 1949

REMARKS: _____

Nº 5241

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/24 1949
RECEIVED OF Raymond Remley FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED J. E. Zell
TO TAP San SEWER, ON THE S SIDE
OF Cherry NE AVE., TYPE OF STREET Paved
ST.,
THE PREMISES BEING LOT NO. 746 HOUSE NO. 323

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.