

9-45

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

Nº 5247

DATE INSPECTED 2-24-49

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_


HOUSE NO. 2611

SIZE OF PIPE USED 6" ~~UP~~ ~~DOWN~~ STREAM TO DITCH AT  
CURB LINE AND DEPTH 78' 5' Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN \_\_\_\_\_ NAME OF CONTRACTOR Boger

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. J. Snyder  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 2-28-49

REMARKS: \_\_\_\_\_

Nº 5247

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/23 1927

RECEIVED OF D. Boyer

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Chas. I. Brink

TO TAP San

SEWER, ON THE S

SIDE

OF Harsh S.E.

AVE.,  
ST.,

TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO. 4316

HOUSE NO. 2611

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR D. Boyer

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.