

9-18

Nº 5248

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-2-49IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM136 -8' deep

HOUSE NO. _____


SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

27TH ST. N.W.

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

3-4-48

REMARKS: _____

Nº 5248

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/1 1919

RECEIVED OF R. Remy

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Don M. Laughlin

TO TAP San

SEWER, ON THE W.

SIDE

OF 27th NW Ept

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT NO. _____

HOUSE NO. _____

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remy

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.