


SR 10-P 16

Nº 5252

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-27-49IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 161SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 23 7'd deepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN YesNAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

25TH ST, S.E.

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-5-49 H.M.D.

REMARKS: _____

Nº 5252

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/24 1949
RECEIVED OF Raymond Remley FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED A.T. Myers
TO TAP San SEWER, ON THE W. SIDE
OF 25th & E. AVE., TYPE OF STREET Alley
THE PREMISES BEING LOT NO. 4923, HOUSE NO. 161

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.