


2-39

Nº 5253

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-23-49IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 819SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 23' 6' deepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN YesNAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Danner St. NE

SIGNED

John Chmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4-22-49

REMARKS: _____

Nº 5253

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/24 1949

RECEIVED OF R. Remley

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Paul Schatz

TO TAP San

SEWER, ON THE W

SIDE

OF Danvers St.

AVE.,
ST.,

TYPE OF STREET

driv

THE PREMISES BEING LOT NO. 2039

HOUSE NO. 819

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.