



N^o 5277

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-25-49IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1278SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 143' 7' deepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN YesNAME OF CONTRACTOR Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3RD ST. S.E.

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-16-49

REMARKS: _____

Nº 5277

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/24 1949
RECEIVED OF Clarence Gibson FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED same
TO TAP San SEWER, ON THE E. SIDE
OF 3rd & E AVE., TYPE OF STREET dirt
THE PREMISES BEING LOT NO. 8236, HOUSE NO. 1278

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Smart

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.