## Nº 5282

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-4 49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	59	8 dech
WAS LATERAL AT CURB? / 5			· ·
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	Bogeri	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING		•
Johnson, ST,	5 E.	/2	
	e de la companya de	1 Blech	
	ancanoniamento,	3	<b>1</b>
•	0 4-7-	19	27
•		manner of the second of the se	b
SIGNED INSPECTOR FOR CITY	FILED AT EN	GINEER'S OFFICE CO	
REMARKS:			

Nº 5282

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohio,	6/3	1949
RECEIVED OF D. Brale		FEE OF \$2	.00
OR WHICH PERMISSION IS GRANTED	J Burn	<del>ett</del>	
O TAPSEWE	R, ON THE	E .	SIDE
F Johnson 16 AVE. TY	PE OF STREET	led	
HE PREMISES BEING LOT NO. 10/17		1010	
VORK TO BE DONE IN ACCORDANCE WITH ORDINANG	CE NO. 2323. DULY PA	ASSED BY THE CITY CO	UNCIL, AND
IAME OF CONTRACTOR 10/80 Ter	· · · · · · · · · · · · · · · · · · ·		

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.