Nº 5284

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-11-49	IF SO HOW AND LOCATI				
HOUSE NO. 1906 SIZE OF PIPE USED 6	DISTANCE FROM FIRST DOWN STREAM TO DITC CURB LINE AND DEPTH	CH ÁT /A	8.	7. dech	
WAS LATERAL AT CURB? Yer		b		•	
WAS ATTACHED TO MAIN			ogen	,	
Lincoln We			- .	,	
	<u>V.</u>			14 TEdes	X
			780	\$ (3) 108	1
1 1 1 0		No.	entere en		C
SIGNED The Control of the INSPECTOR FOR CITY	FILE		'S OFFICE	6-16-49	
REMARKS: Connected	in 19TH 57	. N.E.			

Nº 5284

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

					6/10	4
	10	No.	MASSILLON, OF	110,	710	194 <u>*</u>
RECEIVED (of Davo	un 1	Juge		_ FEE OF \$	
OR WHICH PERM	AISSION IS GRANTED	John	Alln	an		
O TAP	Tunetan	g Sewi	ER, ON THE		north	side
Line	oln Hal	1 🗻	PE OF STREET		parl	_
HE PREMISES BE		5 7	, Hous	ie No. 196	6	
					•	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR DWain OSoge

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.