58 10-P36

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

5292

DATE INSPECTED 6-28-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	40'	7'doch	
HOUSE NO	DISTANCE FROM FIRST MANHOLE			
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?	· · · · · · · · · · · · · · · · · · ·	1 /		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Jans.		
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING S	ERVED.	ì	
South Av	e 5.W	50	Company of the Compan	
			-6'deep	
<u> </u>		<u>کہا</u>	A CONTRACTOR OF THE STREET OF	
		1		
	-	5, 40:18	7 deep	
1050		0 7	outhed in	And the state of t
SIGNED INSPECTOR FOR CIT	FILED AT ENG	INEER'S OFFICE	7-5-49	75
REMARKS:				

Nº 5292

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massil	LON, OHIO,	6/28	194]
RECEIVED OF Chas	Drowde	n	FEE OF \$2	2 00
FOR WHICH PERMISSION IS GRANTED	Atme.			
то тар	SEWER, ON THE	<u> </u>		SIDE
or Lauth AW	AVE. TYPE OF STE	REET OLL	ed	
THE PREMISES BEING LOT NO.	0.7	. House No.	72	
WORK TO BE DONE IN ACCORDANCE	WITH ORDINANCE No. 23	323 DILLY PARCED	DV 200-0	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, A RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR D. Adam

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.