Nº 5294

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-19-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8 deep
WAS LATERAL AT CURB? /c?		*
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LAT		Apr. 1022
Johnson S	7. S.E.	6
N	→	7'deg
	1 2/2	9 / 8'doch
		The control of the co
1.1 51		
SIGNED John Show	FILED AT ENGINEER'S OFFICE	7-15-49
INSPECTOR FOR CIT		
REMARKS:		

Nº 5294

PERMIT TO TAP SEWER

	<i>6</i> :	MASSILLON, OHIO,	7/13	_1947
-	J. W. 1	massicion, Onio,	FEE OF \$2	U I
RECEIVED OF	N IS GRANTED	Q En	well for	· .
TO JAP and		, ON THE	vest	SIDE
or has	AVE. TYP	•	oila	
THE PREMISES BEING LO	ot No. 2/4	8 House No.	937	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.