## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N_{\cdot}^{0}$  5299

| DATE INSPECTED 7-27-49                  | IF SO HOW AND LOCATION FROM Tapped Main 50'  |
|---|--|
| HOUSE NO. 2539                          |  |
| SIZE OF PIPE USED                       | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? No                 |  |
| WAS ATTACHED TO MAIN                    | NAME OF CONTRACTOR AS FOR  |
| SHOW BY DIAGRAM RELATION OF LATE        | ERAL TO WALL OF BUILDING SERVED.   |
|   | N. 8'Deep 1 G2- 11' Deep   |
| Sewer under side                        | e Walk   |
| Sewer under side<br>5. side L. Way East | 50   |
| SIGNED R. J. Jung d                     | FILED AT ENGINEER'S OFFICE 7-2-49 Sectorer   |
| REMARKS: Y not four                     | d. Used saddle hub and tapped  |
| main line                               |  |

## Nº 5299

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

|  | 7/   |
|--|--|
|  | MASSILLON, OHIO, 194                                     |
| RECEIVED OF                            | podonna FEÉ OF \$ 2                                      |
| FOR WHICH PERMISSION IS GRANTED        | One Condonna   |
| TO TAP Cunsilary                       | SEWER, ON THE South                                      |
| - 12 / Part / 8                        | SIDE   |
| 2//2                                   | AVE TYPE OF STREET Jane                                  |
| THE PREMISES BEING LOT NO. 300         | , House No   |
| WORK TO BE DONE IN ACCORDANCE WITH C   | ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND |
| RULES OF THE DEPARTMENT OF PUBLIC SERV | VICE.  |
| NAME OF CONTRACTOR AND AND             | artm   |

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.