

Nº 5301

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14
21

DATE INSPECTED 7-29-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1123

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

? 8' Deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R.F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-2-49

REMARKS:

M.H. not located

Nº 5301

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/30 1949

RECEIVED OF Chet Neuper

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED same

TO TAP San

SEWER, ON THE W

SIDE

OF 4th N E

AVE.,
ST.,

TYPE OF STREET driv

THE PREMISES BEING LOT NO. 10743

HOUSE NO. 1123

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.