## Nº 5305

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-5-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	255	7' L = 94
WAS LATERAL AT CURB? Yes			•
WAS ATTACHED TO MAIN 1	NAME OF CONTRACTOR	dams.	
SHOW BY DIAGRAM RELATION OF LAT			
Sohnson	1.5T. S.E.	255	10 C. V. ex
SIGNED INSPECTOR FOR CIT	FILED AT ENGI	NEER'S OFFICE	for Hg

## Nº 5305

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		86	
≥ <sup>m</sup> s	Massillon, Ohio,		194
RECEIVED OF Mas Told	13 lung	FEE OF \$	}
1	01	4	
OR WHICH PERMISSION IS GRANTED	n //-tr	ind	
1.		,	
O TAP SUMMARIAN SEWER	, ON THE	-to-	SIDE
0.1		molan	510€
8199	E OF STREET	12 09	
HE PREMISES BEING LOT NO.	, House No	1207	
VORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E No. 2323, DULY P	ASSED BY THE CITY C	OUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.			
Robot E. au	Jamo		

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.