

Nº 5308

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-22-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1423

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 47' 5' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Aslon

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Dexter Ave N.E.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 8-11-49

REMARKS: _____

· N^o 5308

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 878 1949

RECEIVED OF W. Aston

FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED Robert Deegan

TO TAP sanitary

SEWER, ON THE south

SIDE

OF Dexter Ave NE

AVE., TYPE OF STREET oiled
ST.,

THE PREMISES BEING LOT NO. 8527

HOUSE NO. 1423

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR W. Aston

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.