

N^o 5326

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14
44
✓

DATE INSPECTED 6-17-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 8

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

93' 7' deep

WAS LATERAL AT CURB?


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Bemley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

OHIO Ave N.W.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Nº 5326

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9-7 1947
RECEIVED OF Robert Robert FEE OF \$ 2⁰⁰
FOR WHICH PERMISSION IS GRANTED Raymond Remley
TO TAP Sanitary SEWER, ON THE North SIDE
OF Ohio Ave. NEW AVE., TYPE OF STREET Dirt ST..
THE PREMISES BEING LOT NO. 4987, HOUSE NO. 8

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.