

Nº 5330

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-1-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1901


SIZE OF PIPE USED 6" 4 DISTANCE FROM FIRST MANHOLE
~~DOWN~~ STREAM TO DITCH AT 15'
CURB LINE AND DEPTH 7' deep

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Woodruff Ave. N.W.



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

Nº 5330

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

9-7

1949

RECEIVED OF

C. Shaffner

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

V.R. Remley

TO TAP

Sanitary

SEWER, ON THE

South

SIDE

OF

Woodroff Ave. NW.

AVE.,
ST.,

TYPE OF STREET

Dirt

THE PREMISES BEING LOT NO.

10282

HOUSE NO.

1901

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.