

Nº 5333

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-15-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1234

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

44'

8' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lennox Ave N.E.



SIGNED

John Ehrmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-13-49

REMARKS: _____

Nº 5333

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

9-7

1949

RECEIVED OF

Warren W. Weisgarber

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

R. Remley

TO TAP

San.

SEWER, ON THE

N.

SIDE

OF

Lennox NE

AVE.,
ST.

TYPE OF STREET

Break

THE PREMISES BEING LOT NO.

8806-8807

HOUSE NO.

1234

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.