

Nº 5334

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

17
✓

DATE INSPECTED 5-26-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 305

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

27'

10' deep

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3 BR ST. N.E.

N. →



SIGNED

John Chinner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-13-49

REMARKS: _____

Nº 5334

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9-7 1947
RECEIVED OF Hugh Spickell FEE OF \$ 2⁰⁰-
FOR WHICH PERMISSION IS GRANTED Raymond Remley
TO TAP Sanitary SEWER, ON THE West SIDE
OF 3rd St. N.E. AVE., TYPE OF STREET Brick
ST.,
THE PREMISES BEING LOT NO. 654, HOUSE NO. 305

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.