

Nº 5341

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3
31

DATE INSPECTED 6-20-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 927

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Seneca Ave



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-13-49

REMARKS: _____

Nº 5341

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Lucy M. 9-7 1942
MASSILLON, OHIO
RECEIVED OF Ill Myers FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Raymond Remley
TO TAP Sanitary SEWER, ON THE North end SIDE
OF Seneca St. NE. AVE., TYPE OF STREET Dirt
ST.,
THE PREMISES BEING LOT NO. 1872, HOUSE NO. 900 927

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.