

N^o 5343

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-15-49IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM1537' deepHOUSE NO. 1624DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHSIZE OF PIPE USED 6"

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way. E.0 153287' deep6' deep7' deep26

SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-23

REMARKS: _____

Nº 5343

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/9 1949

RECEIVED OF A. J. Deana

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED See Application

TO TAP San

SEWER, ON THE N

SIDE

OF Greenway

AVE.,
ST.,

TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 9-46

HOUSE NO. 1624

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Deana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.