

14
47

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 5353

DATE INSPECTED 9-16-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 301



SIZE OF PIPE USED 6" up DISTANCE FROM FIRST MANHOLE
~~DOWN STREET~~ TO DITCH AT 6' upstream 8' deep
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Deluca

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

23 RD ST. N.W.



SIGNED John Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 9-16-49

REMARKS: _____

Nº 5353

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/16 1949
RECEIVED OF Walter Brekone FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Same
TO TAP San SEWER, ON THE W SIDE
OF 23rd St AVE., TYPE OF STREET Robert
THE PREMISES BEING LOT NO. 3704, HOUSE NO. 301
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR De Lucas

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.