

Nº 5367

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14
48
✓

DATE INSPECTED 10-10-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 115

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

65' 9' deep

WAS LATERAL AT CURB? Yes



WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR _____

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

23 RD ST. N.W.



SIGNED _____

John Chmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-10-49

REMARKS: _____

Nº 5367

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/10 1924

RECEIVED OF J. Aston

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Don D Smith

TO TAP San

SEWER, ON THE W.

SIDE

OF 2317th

AVE., TYPE OF STREET driv
ST.,

THE PREMISES BEING LOT NO. 3730

HOUSE NO. 115

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.