

5
47

Nº 5369

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-26-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 740

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

100' 7' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Paloma

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

14th ST. S.E.



SIGNED

John E. Hines
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11-3-49

REMARKS:

Nº 5369

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/18 1949

RECEIVED OF Tom Palmer

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Tom Palmer

TO TAP Sanitary

SEWER, ON THE East

SIDE

OF 14th St E

AVE.,
ST.,

TYPE OF STREET dirt

THE PREMISES BEING LOT NO. 740

8296

HOUSE NO. 740

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Tom Palmer

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.