Nº 5371

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

S.
3.3
Section 2

DATE INSPECTED 10-27-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	5 (4)	
HOUSE NO. 419			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	153'	6-6" Deep
WAS LATERAL AT CURB? Yes		e e e e e e e e e e e e e e e e e e e	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Boger	
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING	SERVED.	
17TH NE	6'Deep	* *	
West Curb Line	6'2 Deep 726	trafficiencia de la compansión de la constantina propriede de la constantina del constantina del constantina de la constantina del constantina	10 the
namen particular and anticonstructive designation of the constructive and anticonstructive an	asianasianasianasianasianasianasianasia	4 Main Sewe	1 in 11 -37,
SIGNED R. T January INSPECTOR FOR CIT	FILED AT EN	GINEER'S OFFICE	
REMARKS:			

Nº 5371

PERMIT TO TAP SEWER

	, make	101	27	
	Massillo	N, OHIO,		194//
		1		700
RECEIVED OF	n 1 000	<u> </u>	FEE OF \$	<u> </u>
FOR WHICH PERMISSION IS GRANTED	1-8-1 B	Elynaur		
FOR WHICH PERMISSION IS GRANTED	7	-		
$\mathcal{L}_{\mathcal{A}} = \mathcal{L}_{\mathcal{A}} = \mathcal{L}_{\mathcal{A}}$		1.	/ /	
TO TAP	SEWER, ON THE			SIDE
or 1741 716	AVE Type of Stree	. 1		
OF	AVE., TYPE OF STREE			
THE PREMISES BEING LOT NO.	9-50	HOUSE NO. 4	9	
THE PREMISES BEING LOT NO.		10052110	:	,
WORK TO BE DONE IN ACCORDANCE WIT	H ORDINANCE No. 232	3. DULY PASSED F	THE CITY C	OUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC S	SERVICE.			
Strain Company of the	7 A .) .			
NAME OF CONTRACTOR			•	

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.