

Nº 5379

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-27-49

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. 910

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

283' 6' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Euclid Ave SW



SIGNED

John Ehmer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS:

Relaid for cellar drain

Relay.

3-5-8

Nº 5379

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/30

1919

RECEIVED OF R. Remley

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED C. E. Remley

TO TAP San

SEWER, ON THE E

SIDE

OF Euclid St.

AVE., TYPE OF STREET Relay  
ST.,

THE PREMISES BEING LOT NO. ~~3269~~ 3262

HOUSE NO. 910

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.