

Nº 5385

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14
34
—

DATE INSPECTED 1-17-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1443

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

14

8' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Keuper

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

San Jose Ave N.E.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-18-50

REMARKS: _____

Nº 5385

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/2 1949

RECEIVED OF Chas. Keuper

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED to tap

TO TAP San

SEWER, ON THE W

SIDE

OF Jarvis N E

AVE., TYPE OF STREET dest
ST.,

THE PREMISES BEING LOT NO. 17 (Out)

HOUSE NO. 1413

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR ~~Chas~~ Keuper

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.