FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-7'-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO.	DISTANCE FROM FIRST MANHOLE		
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	_33	6 decfe
WAS LATERAL AT CURB? Yec		<u></u>	e de la companya del companya de la companya del companya de la co
WAS ATTACHED TO MAIN	ERAL TO WALL OF BUILDING S	Smar!	(
Warick A	ve 2	degli 81	
		2/8	neda e de la Propinsi
		Check	33
and the second of the second o		Margare	n ja jalonna ja ja talanna kaja ja kaja ja
SIGNED INSPECTOR FOR CIT	FILED AT ENG	SINEER'S OFFICE 2	-18-50
REMARKS:			

 N_0

5388

Nº 5388

PERMIT TO TAP SEWER

	MASSILLON, OHIO, //27	50
RECEIVED OF Fred	A A	
FOR WHICH PERMISSION IS GRANTED	Fred m. Dew	
	SEWER, ON THE South	_SIDE
of Namwich HM		
THE PREMISES BEING LOT NO. 354		
WORK TO BE DONE IN ACCORDANCE WITH	H ORDINANCE No. 2323. DULY PASSED BY THE CITY COUNCIL	L, AND
RULES OF THE DEPARTMENT OF PUBLIC S	ERVICE.	

IAME OF CONTRACTOR 11. 1 mant

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.