

Nº 5389

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

7/1 ✓

DATE INSPECTED 2-1-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 705

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

45'

6' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Boger

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Walnut Rd. SW



SIGNED

John E. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-18-50

REMARKS: _____

Nº 5389

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/1 1920

RECEIVED OF D. Bager

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED H. H. Plaskett

TO TAP San

SEWER, ON THE P.

SIDE

OF Bernard St.

AVE.,
ST.,

TYPE OF STREET

Alled

THE PREMISES BEING LOT NO. 4661

HOUSE NO. 705

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bager

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.