

Nº 5397

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

379
269
112

4
41
✓

DATE INSPECTED 4-8-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 724

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

Sw 112' ?
163'

7' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes


NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LAWTON AVE. S.E.

← N

Sw 112'
163'
0



SIGNED John E. Chover
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 4-13-50

REMARKS:

Nº 5397

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

3/15

1945

RECEIVED OF

R. J. Ballenger

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

same

TO TAP

San

SEWER, ON THE

E

SIDE

OF

Lanton St. E.

AVE.,
ST.,

TYPE OF STREET

dist.

THE PREMISES BEING LOT NO.

5180

HOUSE NO.

724

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Dunn

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.