Nº 5405

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

8 3 3
age (Spir.

DATE INSPECTED IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO
SIZE OF PIPE USED CURB LINE AND DEPTH 147
WAS LATERAL AT CURB? / C C
WAS ATTACHED TO MAIN TO NAME OF CONTRACTOR LABREGHT, SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
19th 5t NE.
6 de of
6 vp stream 22.
-6 V STreams
SIGNED FILED AT ENGINEER'S OFFICE 4-13-50
INSPECTOR FOR CITY
REMARKS:

Nº 5405

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

, Massillon, Ohio,	4/3 1950
RECEIVED OF E.K. allrelt	FEE OF \$
FOR WHICH PERMISSION IS GRANTED BILL WARM	des
TO TAP Santan SEWER, ON THE Sant	SIDE
OF 19 M N E AVE TYPE OF STREET.	orla
THE PREMISES BEING LOT NO. 9143-9144 HOUSE NO.	340

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR & More class

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.