

Nº 5430

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-13-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 802

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

106'

7' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Bernard Ave



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5-31-50

REMARKS:

7-23-

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Nº 5430

MASSILLON, OHIO, 5/12 1957

RECEIVED OF Em. P. Buckland, Jr. FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Same

TO TAP San SEWER, ON THE E. SIDE

OF Barnard St. AVE., TYPE OF STREET Alley

THE PREMISES BEING LOT NO. 264, HOUSE NO. 802

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. G. Gator

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.