## Nº 5432

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-19-50 HOUSE NO. 8/5	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7'6 cef1
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Diana	
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED	
Mathias	Ave 10	
	6.40ef	
		7'deef
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	namen en e
REMARKS:		

## LATATION OF PUBLIC SERVICE

. The same $54$	32 PERMIT TO TAP SEWER
	57-
and the second s	MASSILLON, OHIO,
RECEIVED O	FEE OF \$ Deans
and the second of the second o	10021712
TO TAP	SEWER, ON THE
of M	this 77 Live. TYPE OF STREET Leled
THE PREMISES BEIN	a. 20. 26 815
· · · · · · · · · · · · · · · · · · ·	THE CONTRACT WITH OPPINANCE NO. 2323 DULY PASSED BY THE CITY COUNCIL

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.