Nº 5435

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

| DATE INSPECTED 3-25-50 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | |
|---|---|----------------|
| HOUSE NO. | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT | Olland Comment |
| WAS LATERAL AT CURB? | CURB LINE AND DEPTH | |
| WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATER | | oh |
| 27 th st N | · · · · · · · · · · · · · · · · · · · | 3 |
| | 74 | of the second |
| <u>A</u> | | 9.400 |
| | \$20000000 Section 1 | |
| SIGNED INSPECTOR FOR CIT | FILED AT ENGINEER'S | OFFICE 3 3/-50 |

SEE OF OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

| the second of th |
|--|
| Massillon, Ohio, 19 |
| and the second of the second o |
| RECEIVED OF THE OF ST |
| man de la companya del companya del companya de la |
| FOR WHICH PERMISSION IS GRANTED |
| |
| TO TAP SEWER, ON THE SIDE |
| OF 27th nw Cylave. TYPE OF STREET det |
| THE PREMISES BEING LOT NO. 4 3 3 1 , HOUSE NO. 3 1 |
| |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND |
| RULES OF THE DEPARTMENT OF PUBLIC SERVICE. |
| Name of Contractor |

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.