Nº 5440

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-26-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 535	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	5'dec/
WAS LATERAL AT CURB?	NAME OF CONTRACTOR ASTON	
WAS ATTACHED TO MAIN 765	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATE		•
Horrsh Ave.		22 64 cd
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	

TABLE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

5721.	· · · · · · · · · · · · · · · · · · ·
Massillon, Ohio, 19	0
RECEIVED OF January Uston a FEE OF & 2 VV	
Me Sharand	
FOR WHICH PERMISSION IS GRANTED	
TO TAP Danetary SEWER, ON THE South	SIDE
of and are SERVE. TYPE OF STREET dirt	
THE PREMISES BEING LOT NO. 4324-#13 , HOUSE NO. 535	:

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.