FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

5450

DATE INSPECTED 6-19-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	263.	4. 6" dech
WAS LATERAL AT CURB?			r
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR	Aston	
SHOW BY DIAGRAM RELATION OF LATER	the state of the s	RVED.	20044
willow.	(ve NE)		4.
		263	6 decep,
0 / 9 /	And the second s	esta e Pale e se de la companya del companya de la companya del companya de la companya del companya del companya del companya de la companya del com	TO MAKE AND
SIGNED / TILL INSPECTOR FOR CIT	FILED AT EN	GINEER'S OFFICE	
REMARKS:		the electric tax	

FOUR BOXES AND CHARLESONIA MED CALOFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5450 PERMIT TO TAP SEWER

	6/17
1721	MASSILLON, OHIO, 19
RECEIVED OF A TOCKEN	rede FEE OF &
	Echinado 1
FOR WHICH PERMISSION IS GRANTED	
TO TAP lanetary SEWER.	ON THE north SIDE
Willow and MENE THE	OF STREET hard surface
THE PREMISES BEING LOT NO.	, HOUSE NO. 226

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR I arrief Uston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.