-	da f
Tu	Ø

Nº 5463

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-25-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 330		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7. deef
WAS LATERAL AT CURB?		•
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR Keuher	
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.	
INDIANA	AVENE	4
	The state of the s	The second secon
	and the second s	: 1 61e
		1 y 2
the first section of the first section is		1 3
	1 5	15 27 dey
	man A market	and the second of the second s
	<u> </u>	The second secon
SIGNED Control	7-11-	Francisco Company
INSPECTOR FOR CIT	Y TILED AT ENGINEER'S OFFICE	**
	omaldo ela ofre con escriba en occasilar danse e por	
REMARKS:		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	DEIC SERVICE
Nº 5463 PERMIT TO TAP SI	WER
Massillon, Ohio,	19.57
RECEIVED OF CHILA REUSEN	FFF OF \$ 9
	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	§
TO TAPSEWER, ON THE	SIDE
of Alana MAVE. TYPE OF STREET alle	Description of the second
THE PREMISES BEING LOT NO. 107 13 HOUSE NO.	30

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Alugary

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.