

Nº 5472

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-11-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1015

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 93' 8' deep


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

32ND ST. N.W.



SIGNED

John E. Bremer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-6-50

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT NO. 5472

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/3 1950

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED M. J. Schuler

TO TAP San

SEWER, ON THE W

SIDE

OF 32nd NW

AVE.,
ST.,

TYPE OF STREET dirt

THE PREMISES BEING LOT NO. A. 42 205

HOUSE NO. 1015

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.