## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-24-50 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO	
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE  SIZE OF PIPE USED STREAM TO DITCH AT  CURB LINE AND DEPTH 30	7.6. dec/1
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN NAME OF CONTRACTOR Rent /ey	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
32 HP 57, N.W.	j
	2
	1 Kedeel
	MY.
76 de/	/
SIGNED FILED AT ENGINEER'S OFFICE	9 80
INSPECTOR FOR CITY	V/ 57.
REMARKS:	7=1-20
	1 To 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Nº 5473

## A DEPOS OF THE DIRECTOR OF PUBLIC SERVICE

	PERMIT TO TAP SEWER	
	MASSILLON, OHIO,	,50
	RECEIVED OF N. Kemley FEE OF \$	i de
FOR V	WHICH PERMISSION IS GRANTED J. H. LORILO	<u></u>
то та	P SEWER, ON THE	SIDE
OF	Od hill nw AVE. TYPE OF STREET dut	***************************************
: THE P	REMISES BEING LOT NO 12 205 , HOUSE NO. 1021	
Work	TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COL	JNCIL, AND
RULE	S OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.