

Nº 5474

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-24-50

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1057

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

32'

8' deep

WAS LATERAL AT CURB? \_\_\_\_\_

WAS ATTACHED TO MAIN \_\_\_\_\_


NAME OF CONTRACTOR

Rennley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

32' ND ST. N. W.

← N



← 7' deep

8'

32'

10'

SIGNED

John E. Chesser  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-6-50

REMARKS: \_\_\_\_\_

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5474

# PERMIT TO TAP SEWER

MASSILLON, OHIO,

19

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

SIDE

OF

AVE.,  
ST.,

TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

**Note.** This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.