

Nº 5477

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

12
16
52

DATE INSPECTED 3-8-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1227

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Bemley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

9th ST. S.W.



SIGNED

John L. Lamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-6-50

REMARKS: _____

MASSILLON, OHIO, 1950

NO. 5477

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

1950

RECEIVED OF

R. Remley

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Joe Raso

TO TAP

San

SEWER, ON THE

W.

SIDE

OF

9th & W

AVE.,
ST.

TYPE OF STREET

Alled

THE PREMISES BEING LOT NO.

Pl 92 288

HOUSE NO.

1227

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.