Nº 5480

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-23-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	A Long Manager
HOUSE NO. 4/0		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	4. dech
WAS LATERAL AT CURB?		<i>\V</i>
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
16 TH 15 T	Levier Land	
	Mos al	1 4 1 4 0 s/s
SIGNED JALAN INSPECTOR FOR CO		7-6-30
REMARKS:		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5480 PERMIT TO TAP SEWI	ER
RECEIVED OF PEE	1950 2 de
OR WHICH PERMISSION IS GRANTED Ralfell Carnell	
O TAP SEVER, ON THE	, sib
F 16 th nE AVE. TYPE OF STREET CHELLES	<u></u>
HE PREMISES BEING LOT NO 9037-38 HOUSE NO 4/0	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR / Cemley

日本自己的复数形式 有数据的形式 计交换

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.